

FIG. 1




FIG. 2




FIG. 3




FIG. 4

FIG. 4A

FIG. 4B




FIG. 4B




FIG. 5




FIG. 6




FIG. 7




FIG. 8






FIG. 9




FIG. 10




FIG. 11




FIG. 12




FIG. 13




FIG. 14




FIG. 15




FIG. 16A




FIG. 16B




FIG. 17




FIG. 18






FIG. 19A

FIG. 19

FIG. 19A

FIG. 19B





FIG. 19B



## FIG. 20

### READ TRACK INFORMATION

52 01 00 00 00 04 - 00 00 1C 00

### RETURNED DATA

00 1A 04 03 00 04 4F 01 - 00 00 7F 96 00 00 7F 96  
00 04 FE 0F 00 00 00 00 - 00 04 FE 0F

-----  
TRmax = 3

## FIG. 21

### READ Toc (Fmt03h)

43 02 03 00 00 00 - 00 00 31 00

### PMA (Fmt03h) DATA

00 2E 00 00 00 20 00 00 - 41 97 88 00 00 00 00 00  
14 00 01 02 1D 1E 00 00 - 02 00 00 14 00 02 02 25  
23 00 02 1F 1E 00 14 00 - 03 05 2D 25 00 05 09 23  
00 20 00 00 41 97 - 88 00 00 00 00  
00 14 00 01 02 1D - 1E 00 00 02 00  
00 14 00 02 02 25 - 23 00 02 1F 1E  
00 14 00 03 05 2D - 25 00 05 09 23

-----  
CT (3, 1) = 4

CT (3, 2) = 4

CT (3, 3) = 4

ST (3, 1) = 0 : 2 : 0

ST (3, 2) = 2 : 31 : 30

ST (3, 3) = 5 : 9 : 35

## FIG. 22

READ Toc (Fmt02h)

43 02 02 00 00 00 - 01 00 88 00

Toc (Fmt02h) DATA

00	86	01	02	01	14	00	A0	-	62	3B	43	00	01	00	00	01
14	00	A1	62	3B	49	00	02	-	00	00	01	14	00	A2	63	00
04	00	02	25	23	01	14	00	-	01	63	00	0A	00	00	02	00
01	14	00	02	63	00	10	00	-	02	1F	1E	01	54	00	B0	05
07	23	02	4F	3B	48	01	54	-	00	C0	80	00	60	00	61	1B
42	02	14	00	A0	04	07	26	-	00	03	00	00	02	14	00	A1
04	07	2A	00	03	00	00	02	-	14	00	A2	04	07	30	00	05
2D	25	02	14	00	03	04	07	-	36	00	05	09	23	02	54	00
B0	07	0F	25	01	4F	3B	48									
01	14	00	A0	62	3B	-	43	00	01	00	00					
01	14	00	A1	62	3B	-	49	00	02	00	00					
01	14	00	A2	63	00	-	04	00	02	25	23					
01	<u>14</u>	00	<u>01</u>	63	00	-	0A	00	<u>00</u>	<u>02</u>	<u>00</u>					
01	<u>14</u>	00	<u>02</u>	63	00	-	10	00	<u>02</u>	<u>1F</u>	<u>1E</u>					
01	54	00	B0	05	07	-	23	02	4F	3B	48					
01	54	00	C0	80	00	-	60	00	61	1B	42					
02	14	00	A0	04	07	-	26	00	03	00	00					
02	14	00	A1	04	07	-	2A	00	03	00	00					
02	14	00	A2	04	07	-	30	00	05	2D	25					
02	<u>14</u>	00	<u>03</u>	04	07	-	36	00	<u>05</u>	<u>09</u>	<u>23</u>					
02	54	00	B0	07	0F	-	25	01	4F	3B	48					

CT (2, 1) = 4

CT (2, 2) = 4

CT (2, 3) = 4

ST (2, 1) = 0 : 2 : 0

ST (2, 2) = 2 : 31 : 30

ST (2, 3) = 5 : 9 : 35

FIG. 23




FIG. 24




FIG. 25

